



Part Change Customer Notification Form

Date	12/14/2018
EDI Part #:	5050011
Engine Models Affected:	MSG425

Part # Change? (Y/N):	Y
If Yes New Part #:	5040010

Describe Change to Part
<p>ECU update to latest revision from controls vendor. New part is physically the same as the old part and are interchangeable on the engine. No changes to the engine harness are required. Calibration mot files will need to be updated. EDI will update production cals on orders.</p>

Reason for Change
<p>5050011 (GCP) is being discontinued from vendor starting Q1 2019.</p>

Interchangability
<p>Like for like; parts can be swapped directly. New ECU requires the use of the 4G display software for diagnostics, uses the same ECOM cable. Calibration files will have to be Updated to 4G</p>

When Will Change Occur	
Engine Serial # Break for Revised Material:	Engine Serial TBD; targeting January 1st 2019 for change over
Running Change or Replace Inventory?:	Running Change
Service Parts:	5050011 can be ordered through Q2 2019. 5050011 will still be available for WSG1068 Production and legacy service parts.